

Dacia Lodgy

Dacia Lodgy 1.5 dCi "Laureate"













ADULT OCCUPANT

CHILD OCCUPANT





PEDESTRIAN

SAFETY ASSIST

ADULT OCCUPANT

Total 26 pts | 72%

FRONTAL IMPACT



10,7 pts



Passenger



Driver

7,3 pts

SIDE IMPACT POLE

SIDE IMPACT CAR









Pole

REAR IMPACT (WHIPLASH)

1,5 pts

GOOD





ADEQUATE MARGINAL WEAK

POOR

FRONTAL IMPACT

HEAD	
Driver airbag contact	stable
Passenger airbag contact	stable
CHEST	
Passenger compartment	unstable
Windscreen Pillar rearward	26mm
Steering wheel rearward	none
Steering wheel upward	8mm

UPPER LEGS, KNEES AND PELVIS

Chest contact with steering

Stiff structures in dashboard	Steering column; facia end
Concentrated loads on knees	Steering column; facia end
LOWER LEGS AND FEET	
Footwell Collapse	rupture
Rearward pedal movement	brake - 110mm
Upward pedal movement	none

SIDE IMPACT

Head protection airbag	Yes
Chest protection airbag	Yes

WHIPLASH

- Low severity

Seat description	Standard cloth 4 way manual
Head restraint type	Passive
Geometric assessment	0,3 pts
TESTS	
- High severity	0 pts
- Medium severity	2 pts

1,8 pts



CHILD OCCUPANT

Total 38 pts | 77%

18 MONTH OLD CHILD

Restraint Britax-Römer Baby Safy Isofix Plus

Group 0, 0+ **Facing** rearward

Installation ISOFIX anchorages and support

frame



PERFORMANCE 9,4 pts

INSTRUCTIONS 4 pts

INSTALLATION 2 pts

FRONTAL IMPACT

Head forward movement	protected
Head acceleration	good
Chest load	fair

SIDE IMPACT

Head containment	protected
Head acceleration	good

3 YEAR OLD CHILD

Restraint Britax-Römer Duo Plus Isofix

Group 1
Facing forward

Installation ISOFIX anchorages and top tether

PERFORMANCE 10,3 pts

INSTRUCTIONS 4 pts

INSTALLATION 2 pts

FRONTAL IMPACT

Head forward movement	protected
Head acceleration	good
Chest load	fair

SIDE IMPACT

Head containment	protected
Head acceleration	good

VEHICLE BASED ASSESSMENT

6 pts

Airbag warning Label

Text and pictogram on both sides of the passenger sun visor

PEDESTRIAN

Total 16 pts | 44%

 . • [-		,	
	GOO	n	
	GUU	ט	



POOR

SAFETY ASSIST Total 2 pts | 29%

SPEED LIMITATION ASSISTANCE 0 pts

Not assessed

ELECTRONIC STABILITY CONTROL 0 pts (ESC)

Not assessed

Yaw rate ratio (1.00s)	0,00 %
Yaw rate ratio (1.75s)	0,00 %
Lateral displacement (1.07s)	m

SEATBELT REMINDER	2 pts
-------------------	-------

- driver	Pass
- passenger	Pass
- rear	Not assessed

HEAD	9,9 pts
PELVIS	0 pts
LEG	6 pts



DETAILS OF TESTED CAR

SPECIFICATIONS

Tested modelDacia Lodgy 1.5 dCi "Laureate" **Body type**5 door MPV

Year of publication 2012

Kerb weight 1233kg

VIN from which rating applies applies to all Lodgys of the

specification tested

SAFETY EQUIPMENT

Front seatbelt pretensioners driver only

Front seatbelt load limiters

Driver frontal airbag

Front passenger frontal airbag

Side body airbags

Side head airbags

Seatbelt Reminder driver and

passenger

COMMENTS

Adult occupant

In the frontal impact, the screen pillar was heavily deformed at the top of the windscreen and the roof was bent in front of the B-pillar. The rear passenger floor panel and tunnel were completely separated, extending into the driver's footwell and the transmission tunnel was deformed between the front seats. The car was penalised for the instability of its passenger compartment in the test. Dummy readings indicated marginal protection of the passenger's chest and structures in the dashboard presented risk of injury to the knees and femurs of driver and passenger. Protection of the driver's feet and ankles was rated as marginal, owing to deformation and rupture of the footwell area. In the side barrier impact, protection of head, abdomen and pelvis was good and that of the chest was adequate. In the more severe side pole test, dummy readings of rib deformation indicated weak protection of the chest. The seat and head restraint provided poor protection against whiplash injuries in the event of a rear-end collision.

Child occupant

In the frontal test, forward movement of the 3 year dummy, sat in a forward-facing restraint, was not excessive. In the side impact, both the 3 year and 18 month dummies were properly contained by the protective shells of their restraints, minimising the risk of head contact with parts of the car interior. The passenger airbag can be disabled to allow a rearward-facing child restraint to be used in that seating position. However, the airbag switch was poorly labelled and information provided to the driver regarding the status of the airbag was not clear, and the system was not rewarded. The dangers of using a rearward-facing restraint in the passenger seat without first disabling the airbag were clearly labelled in the car.

Pedestrian

The bumper provided good protection for pedestrians' legs in all areas tested and scored maximum points. However, the front edge of the bonnet was poor, and scored nothing. In most areas likely to be struck by the head of a child, the bonnet provided poor or marginal protection. In those areas where an adult's head might strike, protection was predominantly poor.

Safety assist

The Lodgy does not have electronic stability control as standard equipment so it was not assessed by Euro NCAP. A seatbelt reminder is standard on all variants for the driver and passenger seats. A speed limitation device is available as an option but was not assessed by Euro NCAP because it is not standard equipment.